

# Inspection Photos

API: 055-06196

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/2/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06196 | Date: 7/2/2021

## Inspection Photos



**Photo 1.** Facing north along the former access road. The road was not recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 7/2/2021



## Inspection Photos



**Photo 2.** There is gravel and culverts that remain along the road . Arrow points to the culvert that remains.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 7/2/2021

## Inspection Photos



**Photo 3.** Facing west toward the location which was not recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 7/2/2021



## Inspection Photos



**Photo 4.** Facing southwest along the fill slope of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 7/2/2021

## Inspection Photos



**Photo 5.** Facing east along the fill slope of the location. There is scotch thistle which is a List B noxious weed growing along this area shown at red arrows.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 7/2/2021



## Inspection Photos



**Photo 6.** Facing northwest toward the cut slope of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 7/2/2021

## Inspection Photos



**Photo 7.** There are signs of erosion along the upper cut slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 7/2/2021



## Inspection Photos



**Photo 8.** Facing northeast at the location. The area outline consists mostly of weeds; Field bindweed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 7/2/2021

## Inspection Photos



**Photo 9.** View of the location from a distance shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 7/2/2021