

Inspection Photos

API: 055-06186

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/2/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06186 | Date: 7/2/2021

Inspection Photos



Photo 1. Facing east along the former access road. Perennial vegetation cover has not established along the disturbed area of the former road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06186 | Date: 7/2/2021

Inspection Photos



Photo 2. There is Scotch thistle noxious weeds along the former road which needs to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06186 | Date: 7/2/2021

Inspection Photos



Photo 3. Facing northeast along the former road. It appears the gravel and culvert have been removed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06186 | Date: 7/2/2021

Inspection Photos



Photo 4. Facing northeast toward the location. The desirable vegetation has not re-established at the location and there are noxious weeds throughout the disturbed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06186 | Date: 7/2/2021

Inspection Photos



Photo 5. View of ground cover shows dried up noxious weeds; Redstem filaree.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06186 | Date: 7/2/2021

Inspection Photos



Photo 6. Facing northwest at the east side of the location. There is scotch thistle which is a List B noxious weed growing along this area shown at red arrow



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06186 | Date: 7/2/2021

Inspection Photos



Photo 7. Facing west toward the location. The desirable vegetation has not re-established at the location and there are noxious weeds throughout the disturbed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06186 | Date: 7/2/2021

Inspection Photos



Photo 8. Facing southeast at the surrounding undisturbed vegetation which consists of Western wheat, Needle and thread grass, Sand drop seed, among other native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06186 | Date: 7/2/2021

Inspection Photos



Photo 9. 2015 aerial image of the location shows the disturbance area of the location and pit. All associated disturbances must be reclaimed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06186 | Date: 7/2/2021