

Inspection Photos
Operator: Simcoe
API: 067-06505
Date: 7/2/2021



Photo 1. View the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with smooth brome.



Photo 3. View of scattered Scotch thistles within the southwestern project area. Scotch thistles are largely treated, but approximately 20 individuals remain partially treated or untreated.



Photo 4. View the reference area comprised of smooth brome grass field mosaic with sagebrush shrubland with gambel oak, pinyon and juniper, Indian ricegrass, squirreltail, western wheatgrass, and prickly pear.