

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S96W /1SENE

Location ID: 334162



Photo #4343 from entrance to location.



Photo #4344 No battery sign located at the tank battery.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S96W /1SENE

Location ID: 334162



Photo #4346 Undesirable plant species on location.



Photo #4345 Flow line heating insulation open ended and not capped.