

Inspection Photos
Camenisch 1 sx Flowline Release
Spill ID 479713 (AC)



Photo 1 – Dirt being removed from location.



Photo 2 – Spill excavation. Impacts remain in situ.

Inspection Photos
Camenisch 1 sx Flowline Release
Spill ID 479713 (AC)



Photo 3 – Spill excavation. Impacts remain in situ.



Photo 4 – Spill excavation. Impacts remain in situ.