

Inspection Photos
Yoxall Farms Manifold
Spill ID 477437 (AC)/ Remediation Project No. 15961



Photo 1 – Spill area.



Photo 2 – Surficial spill excavation. Impacts remain visible in-situ.