

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402740311

Date Received:
07/07/2021

FIR RESOLUTION FORM

Overall Status: **BOTH**

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

3 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
.	<u>970-563-4000</u>	<u>maralextech@gmail.com</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Hahn, Travis</u>	<u>(970) 563-4000</u>	<u>thahn@maralexinc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903337
Inspection Date: 06/29/2021 FIR Submit Date: 07/01/2021 FIR Status: _____

Inspected Operator Information:

Company Name: MARALEX RESOURCES INC Company Number: 53255
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

LOCATION - Location ID: 320908

Location Name: CONLEY-N32N6W Number: 24NESE County: ARCHULETA
Qtrqtr: NESE Sec: 24 Twp: 32N Range: 6W Meridian: N
Latitude: 37.000710 Longitude: -107.443140

FACILITY - API Number: 05-007-00 Facility ID: 295374

Facility Name: CONLEY Number: 7
Qtrqtr: NESE Sec: 24 Twp: 32N Range: 6W Meridian: N
Latitude: 37.000710 Longitude: -107.443140

CORRECTIVE ACTIONS:

1 CA# 152377

Corrective Action: -Remove equipment Date: 07/02/2021

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment belongs to the surface owner

Equipment is clear of the project area.

Operator
Comment:

COGCC Decision: **Not Approved**

COGCC Representative: Oil and gas equipment and any other materials or equipment on the location, including interim reclamation areas, needs to be removed and properly stored offsite. "Equipment belongs to surface owner" does not meet the standard for a factual review request approval as it is not compliant with the rules.

COGCC Supervisor: Oil and gas equipment and any other materials or equipment on the location, including interim reclamation areas, needs to be removed and properly stored offsite. "Equipment belongs to surface owner" does not meet the standard for a factual review request approval as it is not compliant with the rules.

2 CA# 152378

Corrective Action: -Control weeds around equipment and berms

Date: 07/02/2021

Response: CA COMPLETED

Date of Completion: 07/06/2021

Operator Comment: Weeds are being worked on daily.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

3 CA# 152379

Corrective Action: -Remove and properly dispose of trash and debris.

Date: 07/02/2021

Response: CA COMPLETED

Date of Completion: 07/07/2021

Operator Comment: Trash and debris we picked up and properly disposed of.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

4 CA# 152380

Corrective Action: -Control weeds within interim reclamation areas, re-seed reclamation areas after infestation is controlled.

Date: _____

Response: CA COMPLETED

Date of Completion: 07/07/2021

Operator Comment: Weeds are being controlled by hand until spray can be used.

COGCC Decision: **Not Approved**

COGCC Representative: Per comment below, corrective action is not complete. Hand pulling knapweed is likely to increase knapweed cover.

OPERATOR COMMENT AND SUBMITTAL

Comment: Spray for weeds will be ordered as soon as possible. Surface owner's equipment is clear of the project area.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Travis Hahn Signed: _____

Title: Production Tech Date: 7/7/2021 2:02:40 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402740311	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files