

# Inspection Photos

API: 071-06191

Operator: OGRIS OPERATING LLC

Inspection Date: 7/7/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06191 | Date: 7/7/2021

## Inspection Photos



**Photo 1.** The cattle guard along the main road near the Bingham campground has been maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06191 | Date: 7/7/2021



## Inspection Photos



**Photo 2.** The road was regraded and gravel was applied to area of the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06191 | Date: 7/7/2021



## Inspection Photos



**Photo 3.** It appears recent rain events have deposited sediment into the culverts. Ongoing maintenance needs to be performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06191 | Date: 7/7/2021



## Inspection Photos



**Photo 4.** Sediment has washed into the road from recent rain event. The sediment needs to be removed to establish drainage toward the culvert.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06191 | Date: 7/7/2021



## Inspection Photos



**Photo 5.** Facing northwest along the access road. This area of the road was not repaired. Stormwater is accumulating and has eroded across the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06191 | Date: 7/7/2021



## Inspection Photos



**Photo 6.** Facing northwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06191 | Date: 7/7/2021



## Inspection Photos



**Photo 7.** There is an opening where the steel grate is around the wellhead. This area needs to be covered to prevent wildlife entry. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06191 | Date: 7/7/2021



## Inspection Photos



**Photo 8.** Sign posted on meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06191 | Date: 7/7/2021



## Inspection Photos



**Photo 10.** There does appear to be gravel toward the drip line. Additional gravel may be needed toward the drip line to prevent rutting.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06191 | Date: 7/7/2021