

# Inspection Photos

API: 071-09283

Operator: OGRIS OPERATING LLC

Inspection Date: 7/7/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09283 | Date: 7/7/2021

## Inspection Photos



**Photo 1.** Facing southwest along the access road. There is erosion occurring along the road and gravel has been graded off the road shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09283 | Date: 7/7/2021

## Inspection Photos



**Photo 2.** Erosion is occurring along the road which is not stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09283 | Date: 7/7/2021

## Inspection Photos



**Photo 3.** Erosion is occurring along the road which is not stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09283 | Date: 7/7/2021

## Inspection Photos



**Photo 4.** Facing toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09283 | Date: 7/7/2021