

# Inspection Photos

API: 071-09285

Operator: OGRIS OPERATING LLC

Inspection Date: 7/7/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09285 | Date: 7/7/2021

## Inspection Photos



**Photo 1.** Facing southeast along the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09285 | Date: 7/7/2021



## Inspection Photos



**Photo 2.** Facing toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09285 | Date: 7/7/2021



## Inspection Photos



**Photo 3.** Facing northeast at the well site. The culvert shown at red arrow is filled in with sediment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09285 | Date: 7/7/2021