

Inspection Photos

API: 071-09879

Operator: OGRIS OPERATING LLC

Inspection Date: 7/7/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09879 | Date: 7/7/2021

Inspection Photos



Photo 1. Facing southwest along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09879 | Date: 7/7/2021

Inspection Photos



Photo 2. There are multiple culverts along the road that are filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09879 | Date: 7/7/2021

Inspection Photos



Photo 3. Well sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09879 | Date: 7/7/2021

Inspection Photos



Photo 4. There is oil fluid in the engine skid shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09879 | Date: 7/7/2021

Inspection Photos



Photo 5. The berm around the tank is insufficient to contain a spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09879 | Date: 7/7/2021