

Inspection Photos
Operator: Arkoma
API: 067-05439
Date: 7/7/2021



Photo 1. View the project area from the southern entrance facing center.



Photo 2. View of the northwestern project area from the northern corner facing southwestward. Revegetation is progressing with crested wheatgrass, western wheatgrass, and rubber rabbitbrush.



Photo 3. View of erosional channel forming (approximately 12 inches deep and 12 inches wide) within the northern project area.




Photo 4. View of Russian knapweeds observed within the project are, need to be controlled. Approx. 200 individuals observed.



Photo 5. View the reference area comprised of sagebrush shrubland with understory of western whatgrass, squirreltail, and sunflowers.