

Inspection Photos

Operator: Advanced Wireless
API: 067-09317
Date: 7/7/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with crested wheatgrass, western wheatgrass, and smooth brome.



Photo 3. View of flowering musk thistles and Russian knapweeds within the project area. Approximately 300 individuals observed throughout the project area.



Photo 4. View the reference area comprised of sagebrush shrubland and pinyon/juniper woodland with understory of western whatgrass, squirreltail, buckwheat, and sunflowers.