

Inspection Photos
Operator: Arkoma
API: 067-05412
Date: 7/7/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with crested wheatgrass, western wheatgrass, and smooth brome.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View the reference area comprised of sagebrush shrubland and pinyon/juniper woodland with understory of western whatgrass, squirreltail, buckwheat, and sunflowers.