

Inspection Photos
Operator: Arkoma
API: 067-08193
Date: 7/7/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with crested wheatgrass, western wheatgrass, and smooth brome.



Photo 3. View the reference area comprised of open grass field with western wheatgrass, crested wheatgrass, and smooth brome.