

Inspection Photos

7/08/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 390992

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 390992



Photo 1: Photo taken from the Location, facing north. Photos 1-4 provide an overview of the Location from north, east, south to west.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 390992



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 390992



Photo 3: See comments under photo 1.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 390992



Photo 4: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 390992



Photo 5: Photo taken from the Location. Photo shows desirable plant establishment.



Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 390992



July 7, 2021
39.17160428N 108.1009184W

Photo 6: Photo shows access road reclamation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 390992



Photo 7: Photo shows access road reclamation.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 390992



July 7, 2021

Photo 8: Photo shows access road reclamation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources