

Inspection Photos

7/08/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 312686

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312686



July 7, 2021
39.17820038N 108.0735008W

Photo 1: Photo taken from the west end of the Location, facing north. Photos 1-4 provide an overview of the Location from north, northeast, southeast to south. Photos also show that Final Reclamation has not been performed on the southern portions of the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312686



July 7, 2021
39.1781861N 108.07351937W

Photo 2: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312686



July 7, 2021
39.17818528N 108.07352278W

Photo 3: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312686



Photo 4: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 312686



Photo 5: Photo shows example of noxious weed (Halogeton) establishment observed on the Location.

