

Inspection Photos
Location Name: Hahn 1-4
Location ID: 424891



Photo 1 – Pumping Unit



Photo 2 – Tank Battery



Inspection Photos
Location Name: Hahn 1-4
Location ID: 424891



Photo 3 – Heater Treater and Gas Meter



Photo 4 – ECD and Flare

Inspection Photos
Location Name: Hahn 1-4
Location ID: 424891



Photo 5 – Tank Battery Sign




Photo 6 – Gas Meter Calibration Card

Inspection Photos
Location Name: Hahn 1-4
Location ID: 424891



Photo 7 – Stained Soil at Exhaust



Photo 8 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Hahn 1-4
Location ID: 424891



Photo 9 – Stained Soil at Gas Engine



Photo 10 – Stained Soil at Wellhead