

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 1 – Pumping Unit



Photo 2 – Tank Battery

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 3 – Heater Treater, Gas Meter and ECD




Photo 4 – Wellhead



Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875




Photo 5 – Tank Capacity Label is Fading



Photo 6 – NFPA Label is Fading



Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 7 – Tank Battery Sign



Photo 8 – Gas Engine Exhaust

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 9 – Gas Engine