

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/08/2021

Submitted Date:

07/08/2021

Document Number:

699103998

FIELD INSPECTION FORM

Loc ID 420994 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420980	WELL	SI	02/01/2021	OW	123-32773	SATER C 14-23	SI

General Comment:

[This is a follow up to FIRR #402736811. CA has been corrected](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment:

Weeds have been cut, but will need to be completely removed after the corn has been cut

Corrective Action:

Date:

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 420980 Type: WELL API Number: 123-32773 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 03/09/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 7/8/21 at approximately 0804hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR inspection document #402736811 at Sater C 14-23 of Noble Energy, at Location ID# 420994 in Weld County, Colorado. During this inspection the compliance issue has been corrected to comply with COGCC rules. See attached photos. This is a summary of inspection report.</p>	burnsa	07/08/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103999	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5474710