

Inspection Photos
Location Name: Bighole-Fed Land 15-2
Location ID: 312901



Photo 1. Overview of location taken at entrance facing west.



Photo 2. No bradenhead access apparent. Annual weeds on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Bighole-Fed Land 15-2
Location ID: 312901



Photo 3. Incomplete tank labels. Annual weeds on location.



Photo 4. Raptor nest.

