

Inspection Photos

7/07/2021

Operator: BLACK HILLS / LARAMIE

Location ID: 391178

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 391178



Photo 1: Photo taken from the south end of the Location. Photos 1-5 provide an overview of the Location from west, northwest, north, northeast to east. Photos show Location has meet 1004 reclamation standards.

Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 391178



July 7, 2021
39.18250868N 108.08349254W

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 391178



July 7, 2021
39.18250551N 108.08348667W

Photo 3: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 391178



Photo 4: See comments under photo 1.



Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 391178



July 7, 2021
39.18250438N 108.08348444W

Photo 5: See comments under photo 1.

Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 391178



Photo 11: Photo shows example of noxious weeds observed on the Location.



Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 391178



Photo 12: Photo taken from the south end of the Location, facing south. Photo shows access road has not been reclaimed.

