

Inspection Photos
Location Name: Staudinger 1-31H
Location ID: 424744



Photo 1 – Tank Battery, NFPA Label



Photo 2 – Wellhead



Inspection Photos
Location Name: Staudinger 1-31H
Location ID: 424744



Photo 3 – Wellhead Sign



Photo 4 – Heater Treater

Inspection Photos
Location Name: Staudinger 1-31H
Location ID: 424744



Photo 5 – ECD and Flare




Photo 6 – Gas Meter Calibration Card

Inspection Photos
Location Name: Staudinger 1-31H
Location ID: 424744



Photo 7 – Unused Chemical Tank