



- Photo 1 –





- Photo 2 – Tank battery view southwest





- Photo 3 – Tank battery view northwest





- Photo 4 – Oily soil





- Photo 5 –





- Photo 6 – Upset tank, new spill of unknown liquids within containment



- Photo 7 –





- Photo 8 –





- Photo 9 –





- Photo 10 –





- Photo 11 –





- Photo 12 –





- Photo 13 –