

**Inspection Photos**  
**Location Name: Longmont Farms Unit 5**  
**API 05-123-13222 Spill ID: 479267**



**Photo 1 Well Sign**



**Photo 2 Excavation from south wall looking north.**





**Inspection Photos**  
**Location Name: Longmont Farms Unit 5**  
**API 05-123-13222 Spill ID: 479267**



**Photo 3 Excavation from west side looking east**



**Photo 4 Excavation from northwest corner looking east**





**Inspection Photos**  
**Location Name: Longmont Farms Unit 5**  
**API 05-123-13222 Spill ID: 479267**



**Photo 5 Excavation from northwest corner looking south**



**Photo 6 Piezometer located east of excavation**



**Inspection Photos**  
**Location Name: Longmont Farms Unit 5**  
**API 05-123-13222 Spill ID: 479267**



**Soil stockpile east of excavation**

