

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2021

Submitted Date:

07/09/2021

Document Number:

700702947

FIELD INSPECTION FORM

 Loc ID 335717 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num:
Operator Information:

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|---|-----------------------------|
| , Caerus | | COGCC.inspections@caerus oilandgas.com | |
| Dooling, Jessica | 832-624-0810 | jessica.dooling@exxonmobil.c om | |
| Sutton, Derek | | derek_sutton@xtoenergy.com | |
| clark, Erin | 405-319-3250 | erin.k.clark@exxonmobil.com | Lead regulatory coordinator |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 276625 | WELL | PR | 09/01/2020 | GW | 103-10555 | LOVE RANCH 8 FEE G1 | PR |
| 276786 | WELL | PR | 03/01/2014 | GW | 103-10558 | LOVE RANCH 8 FEE G 4 | PR |
| 276789 | WELL | PR | 07/01/2013 | GW | 103-10557 | LOVE RANCH 8 FEE G3 | PR |
| 276790 | WELL | PR | 07/01/2013 | GW | 103-10556 | LOVE RANCH 8 FEE G2 | PR |
| 277180 | WELL | PR | 01/01/2021 | GW | 103-10559 | LOVE RANCH 8 FEE G5 | PR |
| 278393 | WELL | PR | 03/01/2014 | GW | 103-10599 | LOVE RANCH 8 FEE G8 | PR |
| 278395 | WELL | PR | 02/01/2014 | GW | 103-10601 | LOVE RANCH 8 FEE G7 | PR |
| 279109 | WELL | PR | 07/01/2013 | GW | 103-10616 | LOVE RANCH 8 FEDERAL G10 | PR |
| 279344 | WELL | PR | 07/01/2013 | GW | 103-10621 | LOVE RANCH 8 FEDERAL G9 | PR |
| 298252 | WELL | PR | 02/01/2014 | GW | 103-11379 | LOVE RANCH 8 FEE G6A | PR |

General Comment:

COGCC Inspection Report Summary

On Wednesday 7/7/2021 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at XTO/Caerus Love Ranch #8, at Location # 335717 in Rio Blanco county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

This is a summary of inspection report.

| Location | | | |
|--|--|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action: | | Date: | |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | 911 | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Equipment: | | | |
| Type: Horizontal Heated Separator | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 10 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 5 | | |
| Comment: | chemical tanks three are in metal containment and 2 are in plastic containment | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | pipeline pump | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 276625 | Type: | WELL | API Number: | 103-10555 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 276786 | Type: | WELL | API Number: | 103-10558 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 276789 | Type: | WELL | API Number: | 103-10557 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 276790 | Type: | WELL | API Number: | 103-10556 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 277180 | Type: | WELL | API Number: | 103-10559 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 278393 | Type: | WELL | API Number: | 103-10599 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 278395 | Type: | WELL | API Number: | 103-10601 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 279109 | Type: | WELL | API Number: | 103-10616 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |

Facility ID: 279344 Type: WELL API Number: 103-10621 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID: 298252 Type: WELL API Number: 103-11379 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Culverts | | | | |
| | | Ditches | | | | |
| Berms | | | | | | |
| Ditches | | | | | | |

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 700702960 | photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5475612 |