

Inspection Photos
Location Name: Neff 1
Location ID: 336482



Photo 1 WH sign

Photo 2 weeds all around WH

Inspection Photos
Location Name: Neff 1
Location ID: 336482



Photo 3 Stained soil by WH

Photo 4 No containment under drum in case of spill

Inspection Photos
Location Name: Neff 1
Location ID: 336482



Photo 5 pump jack, meter box, electric panel and transformers