

Inspection Photos
Operator: Simcoe
API: 067-08342
Date: 7/9/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass, smooth brome, and sand dropseed. Irrigation ditch flows along this edge.



Photo 3. View the western project area from the southwestern corner facing northward.



Photo 4. View of reference area comprised of open grass field with western wheatgrass, alfalfa, and smooth brome.