

Inspection Photos  
Operator: Simcoe  
API: 067-06952  
Date: 7/9/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with crested wheatgrass, smooth brome, and sand dropseed.



Photo 3. View the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised of open grass field with smooth brome in a grazed vegetative condition.