

**Inspection Photos**  
**Location Name: New Elk #35-02**  
**Location ID: 308462**



**Photo 1 PIT**

**Photo 2 loc sign**

**Inspection Photos**  
**Location Name: New Elk #35-02**  
**Location ID: 308462**



DATE	CALIBRATED		ORIFICE INSPECTED	PLATE SIZE	GAS SAMPLE TAKEN	COMMENTS
	Y/N	INITIALS				
1-13-16	YES	MM	YES	1.000	NO	verified
03-15-16	NO	JP	NO	1.000	yes 0.5604	Gas Analysis J. Petree
7-20-16	NO	MM	YES	0.875	NO	PLATE TO 0.875
1-10-17	YES	MM	YES	0.875	NO	verified
03-06-17	NO	JP	NO	0.875	yes 0.5619	Gas Analysis J. Petree
1-23-18	YES	MM	YES	0.875	NO	verify
1-15-19	YES	MM	YES	0.875	NO	verified
1-6-20	YES	MM	YES	0.875	NO	verified
1-21-21	YES	LS	YES	0.875	NO	cal STD ver JP DP

Colorado Oil and Gas Conservation Commission  
 37.13117, -104.96486, 2344.9m  
 Jul 6, 2021 12:28:19



**Photo 3 meter calibration card**

**Photo 4 fluid in compressor skid about to run over.**