

**Inspection Photos**  
**Location Name: New Elk #35-09**  
**Location ID: 308692**



Colorado Oil and Gas Conservation Commission  
37.12614, -104.9573, 2507.0m  
Jul 6, 2021 13:37:36



Colorado Oil and Gas Conservation Commission  
37.1262, -104.95732, 2506.6m  
Jul 6, 2021 13:38:20

**Photo 1 Skid full of fluid.**

**Photo 2 loc sign**

**Inspection Photos**  
**Location Name: New Elk #35-09**  
**Location ID: 308692**

DATE	CALIBRATED		ORIFICE INSPECTED	PLATE SIZE	GAS SAMPLE TAKEN	COMMENTS
	Y/N	INITIALS				
2-4-15	y	AA	yes	.500	no	Cal DPSPRTD verified
03-10-15	no	JP	no	.500	yes 0.565	GAS ANALYSIS J. Petree
2-4-16	y	AA	no	.500	yes 0.565	ver RTD Cal SPDP
03-16-16	no	JP	y	.500	no	ver RTD Cal SPDP
2-6-17	y	AA	y	.500	yes 0.565	GAS ANALYSIS J. Petree
03-07-17	no	JP	no	.500	no	ver RTD Cal SPDP
2-27-18	yes	AA	yes	.500	yes 0.513	GAS ANALYSIS J. Petree
2-4-19	yes	AA	yes	.500	no	ver All
2-12-20	yes	MM	yes	.500	no	ver RTD
2-23-21	yes	LG	no	.500	no	ver DPSP Cal RTD

Colorado Oil and Gas Conservation Commission  
 37.1262, -104.95727, 2506.1m  
 Jul 6, 2021 13:38:51



Colorado Oil and Gas Conservation Commission  
 37.12616, -104.95721, 2498.3m  
 Jul 6, 2021 13:39:27

**Photo 3 meter calibration card.**

**Photo 4 loc pic**