


**Inspection Photos**  
**Location Name: AC #5-12, 5-12V**  
**Location ID: 333460**



**Photo 1 AC 5-07 meter house and well head sign**

**Photo 2 meter calibration card**

**Inspection Photos**  
**Location Name: AC #5-12, 5-12V**  
**Location ID: 333460**



**Photo 3 5-12 well head**



**Photo 4 5-12v production equipment.**

**Inspection Photos**  
**Location Name: AC #5-12, 5-12V**  
**Location ID: 333460**

07/10/2017

DATE	CALIBRATED		ORIFICE INSPECTED	PLATE SIZE	GAS SAMPLE TAKEN	COMMENTS
	Y/N	INITIALS				
8-27-13	yes	JCA	Charged	1.00	no	JJA cal. b. sp. sp.
7/14/14	N	↑	N	1.00	yes/3632	Gas Analysis KTD
8-7-14	YES	L.H.	YES	1.000	NO	CAL SPE DP.
6-3-15	yes	AA	yes	1.000	no	yes DP SP RTD Equat.
07-06-15	NO	SP	NO	1.000	yes 0.5615	Gas Analysis J. Petro
6-6-16	yes	AA	yes	.875	no	yes DP RTD Cal SP Plate
07-8-16	no	SP	NO	0.875	yes 0.5611	Gas Analysis J. Petro
6-8-17	yes	AA	yes	.875/.150	no	yes RTD Cal SP Plate Cal
9/10/17	N	↑	N	.750	✓-5651	Gas KTD TA
6-27-18	yes	MM	yes	.750	no	yes RTD
6-27-19	yes	MM	yes	.750	no	yes RTD
6-4-20	yes	MM	yes	.750	no	yes RTD
6-17-20	yes	JC	no		no	yes RTD

Colorado Oil and Gas Conservation Commission  
 37.11159, -104.91619, 2291.5m  
 Jul 8, 2021 11:38:45

Photo 5 5-12v meter calibration card..