

Inspection Photos
Operator: Simcoe
API: 067-09648
Date: 7/9/2021



Photo 1. View the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with grasses such as smooth brome, intermediate wheatgrass, blue grama, and crested wheatgrass.



Photo 3. View the eastern project area from the southeastern corner facing northward.



Photo 4. View the reference area comprised of open grass field with crested wheatgrass, western wheatgrass, and smooth brome.