

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE /2-W-27

Location ID: 335233



Photo #4374 from entrance to location.



Photo #4375 from entrance to location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE /2-W-27

Location ID: 335233



**Photo #4376 Wellhead sign weathered and not legible.**



**Photo #4377 Stained soils at wellheads.**

