

Inspection Photos

Location Name: CAERUS PICEANCE LLC PUCKETT-67S97W /1NESE

Location ID: 324313



Photo #4385 from entrance to location.



Photo #4386 flow line heating insulation opened ended and not capped.

