

# Inspection Photos

7/12/2021

Operator: NONSUCH NATURAL GAS INC #  
10163

Location ID: 324169  
Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



**Photo 1:** Photo taken from the west end of the Location, facing north. Photos 1-4 provide an overview of the Location from north, northeast, southeast to south.

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



July 12, 2021  
39.51420048N 108.20027876W

**Photo 2:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



July 12, 2021  
39.51420214N 108.20027204W

**Photo 3:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



July 12, 2021  
39.51419952N 108.20026781W

**Photo 4:** See comments under photo 1.



## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



**Photo 5:** Photo taken from the west end of the Location, facing west. Photo shows interim areas; unable to find evidence of additional reclamation work; control measures to stabilize seeded soils not implemented. Photo also shows control measures to protect/stabilize cut/fill slopes of the Location, and prevent offsite sediment transport remains missing or insufficient.



## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



**Photo 6:** Photo taken from the west end of the Location, facing northwest. See comments under photo 5 regarding interim reclamation and stormwater/erosion control BMPs.



## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



**Photo 7:** Photo taken from the west end of the Location, facing north. See comments under photo 5 regarding interim reclamation and stormwater/erosion control BMPs.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Operator Name: NONSUCH NATURAL GAS INC # 10163  
Location ID: 324169



**Photo 8:** Photo shows example of noxious weeds (Houndstongue) observed on the Location.

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



**Photo 10:** Photo taken from the east end of the Location, facing north. See comments under photo 5 regarding interim reclamation and stormwater/erosion control BMPs.

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



**Photo 11:** Photo taken from the west end of the Location, facing east. See comments under photo 5 regarding interim reclamation and stormwater/erosion control BMPs.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



**Photo 12:** Photo shows example of Noxious weeds (Bull thistle) observed on the Location.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



**Photo 13:** Photo shows hydrocarbon accumulation within the pit on Location.



## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



**Photo 14:** Photo shows hydrocarbon accumulation within the pit on Location.

