

Inspection Photos

7/12/2021

Operator: LARAMIE ENERGY LLC #10433

Location ID: 324315

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 324315



Photo 1: Photo taken from the access road northeast of the Location, facing southwest. Photo shows interim reclamation of areas not needed for production has not been performed in accordance with 1003 Rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 324315



Photo 2: Photo taken from the southeast end of the Location, facing northwest. Photo shows interim reclamation of areas not needed for production has not been performed in accordance with 1003 Rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 324315



Photo 3: Photo taken from the east end of the Location, facing north. Photo shows control measures to protect/stabilize the cut slopes of the Location remain missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 324315



Photo 4: Photo taken from the east end of the Location, facing southwest. Photo shows control measures to protect/stabilize the cut slopes of the Location remain missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 324315



July 12, 2021
39.53914636N 108.20728911W

Photo 5: Photo taken from the south end of the Location, facing west. Photo shows control measures to protect/stabilize the fill slopes of the Location remain missing or insufficient.