

# Inspection Photos

7/12/2021

Operator: LARAMIE ENERGY LLC #10433

Location ID: 335647

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 335647



**Photo 1:** Photo taken from the south end of the Location, facing northwest. Photos 1-3 provide an overview of the Location from northwest, north to northeast. Photos show interim reclamation of areas not needed for production on the Location, and on the 2<sup>nd</sup> access road to the Location, has not been performed.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 335647



July 12, 2021  
39.54802869N 108.21076978W

**Photo 2:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 335647



July 12, 2021  
39.54802241N 108.21076344W

**Photo 3:** See comments under photo 1.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 335647



**Photo 4:** Photo taken from the southeast end of the Location, facing northeast. Photo shows areas of the Location not needed for production, as well as a 2<sup>nd</sup> access road, have not been reclaimed.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 335647



**Photo 5:** Photo taken from the fill slopes of the Location. Photo shows control measures to protect/stabilize slopes of the Location are missing or insufficient.





Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 335647



**Photo 6:** Photo taken from the fill slopes of the Location. Photo shows control measures to protect/stabilize slopes of the Location are missing or insufficient.





Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 335647



**Photo 7:** Photo taken from the fill slopes of the Location. Photo shows control measures to protect/stabilize slopes of the Location are missing or insufficient.





Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 335647



**Photo 8:** Photo taken from the cut slopes on the east end of the Location. Photo shows control measures to protect/stabilize slopes of the Location are missing or insufficient.