

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-67S95W /6NWNE

Location ID: 334920



Photo #4409 from entrance to location.



Photo #4410 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-67S95W /6NWNE

Location ID: 334920



**Photo #4411 Location lacks stabilization.**



**Photo #4412 Location lacks stabilization.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-67S95W /6NWNE

Location ID: 334920



**Photo #4413 No form of tracking BMP located at entrance to location.**