

**Inspection Photos**  
**Location Name: Hendershot 1**  
**Location ID: 317497**



**Photo 1 – Heater Treater**



**Photo 2 – Wildlife Screen Installed**

**Inspection Photos**  
**Location Name: Hendershot 1**  
**Location ID: 317497**



**Photo 3 – Tank Battery**



**Photo 4 – Berms Repaired**

**Inspection Photos**  
**Location Name: Hendershot 1**  
**Location ID: 317497**



**Photo 5 – Tank Signage**



**Photo 6 – Heater Treater – Berms installed**

**Inspection Photos**  
**Location Name: Hendershot 1**  
**Location ID: 317497**



**Photo 7 – Manifold – Weed Re-Growth – Unused Pipe has been removed**



**Photo 8 – Tank Battery Sign**

**Inspection Photos**  
**Location Name: Hendershot 1**  
**Location ID: 317497**



**Photo 9 – Pit Area – Weed Re-Growth**



**Photo 10 – Pit Area – Weed Re-Growth**

**Inspection Photos**  
**Location Name: Hendershot 1**  
**Location ID: 317497**



**Photo 11 – Pit Area – Weed Re-Growth**



**Photo 12 – Heater Treater Area – Weed Re-Growth**

**Inspection Photos**  
**Location Name: Hendershot 1**  
**Location ID: 317497**



**Photo 13 – Pumping Unit Area – Weed Re-Growth**



**Photo 14 – Pumping Unit**



**Inspection Photos**  
**Location Name: Hendershot 1**  
**Location ID: 317497**



**Photo 15 – Wellhead – Unmarked Riser – Weed Re-Growth**