

Inspection Photos
Operator: Simcoe
API: 067-07631
Date: 7/13/2021




Photo 1. View the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing in portions with western wheatgrass, crested wheatgrass, and rubber rabbitbrush.



Photo 3. View the southern project area from the southwestern corner facing eastward.



Photos 4/5 View of debris within the western project area.



Photo 6. View the reference area comprised of sagebrush shrubland and pinyon/juniper woodland, Indian ricegrass, squirreltail, prickly pear, narrowleaf yucca, and threadleaf sunflower.