

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WRIGHT, SMALLWOOD, CASTEEL-67S96W /27SENW

Location ID: 334744



Photo #4418 from entrance to location.



Photo #4419 No sign located at the tank battery.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WRIGHT, SMALLWOOD, CASTEEL-67S96W /27SENW

Location ID: 334744



**Photo #4420 Location lacks stabilization.**



**Photo #4421 Location lacks stabilization.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WRIGHT, SMALLWOOD, CASTEEL-67S96W /27SENW

Location ID: 334744



**Photo #4423 Tracking BMP insufficient.**