

Inspection Photos
Location Name: Flaherty PAD
Location ID: 443962



Photo 1 – Tank Battery



Photo 2 – Separators

Inspection Photos
Location Name: Flaherty PAD
Location ID: 443962



Photo 3 – VRU



Photo 4 – Gas Meters

Inspection Photos
Location Name: Flaherty PAD
Location ID: 443962



Photo 5 – Tank Battery Sign



Photo 6 – Tank Battery Sign

Inspection Photos
Location Name: Flaherty PAD
Location ID: 443962



Photo 7 – 18-13-12 Wellhead – Stained Soil



Photo 8 – 18-13-12 Wellhead – Stained Soil

Inspection Photos
Location Name: Flaherty PAD
Location ID: 443962



Photo 9 – Unused Rods



Photo 10 – Unused Tubing

Inspection Photos
Location Name: Flaherty PAD
Location ID: 443962



Photo 11 – 18-13-12 Wellhead – Stained Soil



Photo 12 – 18-13-12 – Unmarked Riser

Inspection Photos
Location Name: Flaherty PAD
Location ID: 443962



Photo 13 – 18-7-10 Wellhead – Stained Soil



Photo 14 – 18-7-10 Wellhead – Stained Soil

Inspection Photos
Location Name: Flaherty PAD
Location ID: 443962



Photo 15 – Unused Tubing and Rods



Photo 16 – 18-13-15 Wellhead – Stained Soil

Inspection Photos
Location Name: Flaherty PAD
Location ID: 443962



Photo 17 – Unmarked 2” Risers at VRU