

**Inspection Photos**  
**Location Name: Middlepark 18 PAD**  
**Location ID: 442024**



**Photo 1 – Location Sign at Entrance**

**Photo 2 – NE Tank Battery**

**Inspection Photos**  
**Location Name: Middlepark 18 PAD**  
**Location ID: 442024**



**Photo 3 – Containment missing Wildlife netting**



**Photo 4 – Trash in NE Corner of Location**



**Inspection Photos**  
**Location Name: Middlepark 18 PAD**  
**Location ID: 442024**



**Photo 5 – State Seventy Holes J-18**



**Photo 6 – MiddlePark 18-5-4L Wellhead**



**Inspection Photos**  
**Location Name: Middlepark 18 PAD**  
**Location ID: 442024**



**Photo 7 – Middlepark 18-21-3L Wellhead**



**Photo 8 – Separators**





**Inspection Photos**  
**Location Name: Middlepark 18 PAD**  
**Location ID: 442024**



**Photo 9 – Unmarked Riser**



**Photo 10 – South Compressor**



**Inspection Photos**  
**Location Name: Middlepark 18 PAD**  
**Location ID: 442024**



**Photo 11 – VRU**



**Photo 12 – Stained Soil at West VRT**



**Location ID: 443962**

**Photo 13 – Stained Soil at SW Corner of Tank Battery**



**Photo 14 – Unmarked Riser at SE Corner of Tank Battery**

**Inspection Photos**  
**Location Name: Middlepark 18 PAD**  
**Location ID: 442024**



**Photo 15 – ECD**



**Photo 16 – Compressor**





**Inspection Photos**  
**Location Name: Middlepark 18 PAD**  
**Location ID: 442024**



**Photo 17 – Compressor Drain Pit missing Capacity Label**



**Photo 18 – Compressor Day Tanks**



**Inspection Photos**  
**Location Name: Middlepark 18 PAD**  
**Location ID: 442024**



**Photo 19 – Tank Drain Pit missing Capacity Label**