

Inspection Photos
Location Name: Smith Rancho 1-14
Location ID: 316751



Photo 1. Overview of location taken facing west.



Photo 2. Stained soil on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Smith Rancho 1-14
Location ID: 316751



Photo 3. Wellhead sign not updated to current sign rule.



Photo 4. Battery sign not updated to current sign rule. Tank label not updated to current tank label rule.

