

**Inspection Photos**  
**Location Name: Peoc-NVG 41-23H**  
**Location ID: 316766**



**Photo 1. Overview of location taken facing north.**



**Photo 2. Old operator on location sign.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Peoc-NVG 41-23H**  
**Location ID: 316766**



**Photo 3. Old operator and incomplete tank label.**



**Photo 4. Incomplete battery sign.**





**Inspection Photos**  
**Location Name: Peoc-NVG 41-23H**  
**Location ID: 316766**



**Photo 5. Stained soil.**



**Photo 6. Stained soil.**



**Inspection Photos**  
**Location Name: Peoc-NVG 41-23H**  
**Location ID: 316766**



**Photo 7. Stained soil.**



**Photo 8. Stained soil.**





**Inspection Photos**  
**Location Name: Peoc-NVG 41-23H**  
**Location ID: 316766**



**Photo 9. Incomplete tank labels.**

