

# Inspection Photos

7/12/2021

Operator: LARAMIE ENERGY LLC #10433

Location ID: 335889

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 335889



**Photo 1:** Photo taken from the Location, facing west. FIRR No. 402706390 shows Operator installed a soil binder and mulch on the cut slopes of the Location. Photo show BMP is not in proper functioning condition; BMP not adequate for the site's conditions to protect and stabilize cut slopes of the Location.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 335889



July 12, 2021  
39.53137893N 108.22341677W

**Photo 2:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 335889



**Photo 3:** See comments under photo 1. Erosion degradation evident.





Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 335889



**Photo 4:** Photo taken from the cut slopes on the North end of the Location, facing north. Photo shows BMPs to protect and stabilize the cut slopes of the Location remain missing or insufficient.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 335889



**Photo 5:** Photo taken from the cut slopes on the North end of the Location, facing north. Photo shows BMPs to protect and stabilize the cut slopes of the Location remain missing or insufficient.