

Inspection Photos

7/12/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335961

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335961



Photo 1: Photo taken from the east end of the Location, facing southwest. Photos 1-4 provide an overview of the Location from north, northeast, southeast to south. Photos show interim reclamation has been performed, and is in process.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335961



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335961



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335961



July 12, 2021
39.56147156N 108.28534051W

Photo 4: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335961



July 12, 2021
39.56147067N 108.28534069W

Photo 5: Photo shows unused t-post and fence equipment stored on the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335961



July 12, 2021
39.56134132N 108.28515115W

Photo 6: Photo shows unused pipeequipment stored on the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335961



July 12, 2021

Photo 7: Photo taken from the north of the Location, facing south. Photo shows former access road that ran on the west end of the Location, and accessed the site from the south has been reclaimed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources