



Whiting Oil & Gas Corporation

Wildhorse 06-0634H Release Photo Documentation

Location ID: 427410

Sec 6 9N 59W

7/16/2021



View of initial clean up



Source Area
Red arrow indicates failure point