

**CHEVRON USA INC - 16700**  
**API# 05-103-06125 GRAY #B-9**  
**Inspection Date : 7/14/2021**



Injection wellhead during MIT

**State of Colorado**  
**Oil and Gas Conservation Commission**  
**MECHANICAL INTEGRITY TEST**

Form 21  
 Rev. 3/15

1. All parts of this permit test must be completed within 24 hours.  
 2. This form is to be completed by the permit holder or a representative of the permit holder.  
 3. This form is to be completed by the permit holder or a representative of the permit holder.  
 4. This form is to be completed by the permit holder or a representative of the permit holder.  
 5. This form is to be completed by the permit holder or a representative of the permit holder.

Operator: Chevron U.S.A. Inc.  
 Address: 1500 Cheyenne Road  
 City: Arleta  
 State: CO  
 Zip: 81648  
 Phone: (970) 675-3842  
 Email: all@chevron.com

Well Name: 05-103-06125  
 Well ID: 05-103-06125  
 Well Type: Injection  
 Well Depth: 24  
 Well Status: 19  
 Well Completion: 19

Test Type: ☒ SHUT-IN PRODUCTION WELL ☒ INJECTION WELL  
☐ Test to Maintain S/A Status ☐ 3-year UIC  
☐ Verification of Repairs ☐ Annual UIC Test

Test Date: 7/14/2021  
 Test Time: 09:14  
 Test Location: 6278-6547  
 Test Depth: 6043.08'

Inspector Name: Arleta Sanford  
 Inspector Title: Permitting Specialist  
 Inspector License Number: 633803462  
 Inspector Date: 07/14/2021

Form 21 field copy